


fischertechnik Turn Conveyor



Terminal no.	function	input/output
1	power supply (+) actuators	24vdc
2	power supply (+) sensors	24vdc
3	power supply (-) actuators	0v
4	power supply (-) sensors	0v
5	inside conveyor belt photo sensor	input01
6	puscher back limit switch	input02
7	puscher forward limit switch	input03
8	outside conveyor belt photo sensor	input04
9		
10		
11		
12		
13		
14		
15	inside conveyor drive	output01
16	puscher motor forward	output02
17	puscher motor backward	output03
18	outside conveyor drive	output04
19		
20		
21		
22		
23		
24		
25		
26		

